

Address of premises

Garbutt QLD 4814

CORAL SEA PROPERTY MANAGEMENT

621 Flinders St

T: 07 4724 1723 coralseaproperty.com.au

Townsville City QLD 4810

General Comments:

Overall Standard:

Our inspector noticed the lawn had not been mowed. A follow up will be done on 2/07/2020 and photos of the mowed lawn will be sent through.

Recommended Maintenance:


ROUTINE INSPECTION REPORT

Q

Tenant's name(s)

83 Gorden St

Bronte Roberts & Ashlea Sergeant & Britney Robson



ACTION CODES

YES NO

This tenancy inspection report is a visual one carried out by Coral Sea Property Management to assess the manner in which the tenant is maintaining your property. As your property manager, our role is to manage the tenancy; We are not qualified to assess the structural aspects of areas including but not limited to staircases, decking and balconies or to ensure that plumbing, electrical or gas mixtures of fittings, glass windows, doors and balustrades, smoke alarms, asbestos, swimming pool safety barriers (and associated fittings) comply and operate in accordance with applicable building/council codes and/or laws and regulations. The inspection does not include the moving of furniture, lifting of floor coverings, inspecting the interiors of roof spaces, under flooring, inside of cupboards, tenant's goods of other belongings. Coral Sea Property Management recommends that all landlords have regular inspections carried out by suitable qualified, licensed and insured contractors and experts in the appropriate areas when necessary. Coral Sea Property Management also recommends that all landlords hold adequate insurance, including landlords insurance.

Your tenant is taking extremely good care of the home. The property is presented in excellent condition. Floors and walls clean, tenant belongings presented neat and

tidy, wet areas free of mold and no visible tenant damages or maintenance concerns. The tenant put in a clear effort for this inspection.

Work to be carried out by Landlord:

Inspector Signature

Frankh

26/06/20 Date


Address of premises 83 Gorden St,Garbutt QLD 4814

	Condition Satisfactory	Action required by tenant	Action required by landlord	Inspector Comments
Areas				
Exterior 2				Refer to media: 1 2 3 4 5 6
Entrance Hall				Refer to media: 7 8 9 10 11 12 13 14 15 16 17
Lounge Room				Refer to media: 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36
Kitchen				Refer to media: 57 58 59 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61
Dining Room				
Ensuite				Refer to media: 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
Bedroom				Refer to media: 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101
Bedroom 2				Refer to media: (102) (103) (104) (105) (106) (107) (108) (109) (110) (111) (112) (113) (114) (115) (116) (117) (118) (119) (120)
Bedroom 3				Refer to media: 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145
Bedroom 4				Refer to media: 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161
Toilet				
Bathroom				
Bathroom 2				Refer to media: (162) (163) (164) (165) (166) (167) (168) (169) (170) (171) (172) (173) (174) (175) (176) (177) (178) (179) (180) (181) (182) (183) (184) (185)
Bathroom 3				
Laundry				
Exterior				Refer to media: (186 (187 (188 (189 (190 (191 (192 (193 (194 (195 (196 (197 (198 (199 (200 (201 (202 (203 (204 (205 (206 (207 (208 (209 (209 (201 (201 (201 (201 (201 (201 (201 (201
Garage				

Inspector Signature

Frath






hath


Date 26/06/20





hath






Frath

Date 26/06/20






Frath


Date 26/06/20





Frath






Inspector Signature Haith


Date 26/06/20






Frath






Frath






Inspector Signature Haith





hath






Frath

Date 26/06/20






Frath


Date 26/06/20






Frath





Frath






Frath

Date 26/06/20






Frath


Date 26/06/20






Frath





Frath






Frath


Date 26/06/20





Frath






hath

Address of premises 83 Gorden St,Garbutt QLD 4814






Inspector Signature

hath






Frath


Date 26/06/20






Frath





Frath






Frath

Date 26/06/20






Frath

Date 26/06/20

Address of premises 83 Gorden St,Garbutt QLD 4814






Inspector Signature

Frath


Date 26/06/20






Frath






Frath





hath






Frath

Date 26/06/20






hath


Date 26/06/20






Frath





Frath






hath

Date 26/06/20






hath

Date 26/06/20






Frath


Date 26/06/20






Frath






Frath



Frath






Frath

Date 26/06/20

Address of premises 83 Gorden St,Garbutt QLD 4814






Inspector Signature

Frath






Frankh

Date 26/06/20






Frath

Date 26/06/20






Frath

Date 26/06/20






hath


Date 26/06/20





hath






hath

Date 26/06/20






Frath


Address of premises 83 Gorden St,Garbutt QLD 4814





Inspector Signature Haith





Frath





Frath